ME537 - PRODUCT REALIZATION										
PROJECT NAME	E 3D Tic Tac Toe									
	Tim, Jon									
	Mikey, Namrah									
TEAM MEMBERS	Sung Won	SUPERVISOR	Anna Thornton							
DATE	March 25, 2020	AUTHORS								
DOCUMENT TRACKING										
VERSION	EDITS COMPLETED BY	DATE	DESCRIPTION OF EDIT							
1.0	Sung Won	03/19/2020	Created DFMEA							

Item			Potential Effect(s) of	(1 mild - 10	Potential Cause(s)/ Mechanism(s) of	Occurence (1 seldom -		Detection (1 easy -		Recommended	Responsibility and Target Completion					
number	Item and fuction	Mode	Failure	severe)	Failure	10 often)	Design Controls	10 hard)	RPN	Action(s)	Date	Action Results	Severity	Occurence	Detection	RPN
							cut smaller than the									
							inner dimension of box.									
							Slots on the box cut			Check the slots are						
					Incorrect tolerance,		first before cutting the			straight and cut all the						
	Acrylic board sliding		Forcing and		misalighnment of		wood into 4 individual			way through before						
1.1	through slots	Stuck	breaking	7	slots	2	panels.	200.00%	28	cutting into 4 panels						0
							Slots cut to be slightly			Cut the slots withe						
							wider than the			lower tolerance first						
	Acrylic board		Pieces fall out				thickness of the acrylic			and then cut wider if						
1.2	staying on the box	Slides off the box	of the box	8	Incorrect tolerance	2	board Tolerance aagea so	300.00%	48	needed						0
							that pieces connect									
		Pieces do not fit			Incorrect tolerance.		and disconnect with									
			Game canot		stubs wear down		minimal force. Life			SPC for the fits of the						
21			be played		over time	3	testing for pieces.	300.00%	81	pieces						0
2.11	oraciang pieces	40 1101 31 40K	Do piayou		0.00.11110		rosinig for piocoss.	000.0070	0.	pieces						Ť
					Incorrect number of											
					pieces packaged					Add functionality test						
	Sufficient number of		Game cannot		with the box, user		Minium of 14 pieces of			to check the number						
2.2	pieces for each type	Missing piece	be played	9	loses piece(s)	2	each type packaged	300.00%	54	of pieces						
										Add extra game						
			Full game		Poor quality of cast,		Ensure quality meets			pieces in case the						
	Fitment peg breaks		cannot be		too much force is		standards and that size			pieces in case me						
			played		applied, fit too tight	2	is within spec	200.00%	20	breaks, or wears down						
2.3		Rope tears or	piayeu		Rope not properly		is willinspec	200.00%	20	breaks, or wears down	 	 		 	†	
	Rope carrying the	disconnects from	Box cannot be		tied, low durability					Add durability test for						
3.1	box	the box	carried	4	of rope	1	High quality rope used	200.00%	8	rope		1				0
					Repeated dropping									1		
			Pieces cannot		or force applied to		High quality and sturdy			Perform drop test for						
4.1	Box stores pieces	cracks	be stored	7	box	3	wood used	300.00%	63	the product						0
							Wood sanded down									
1	Box easy and safe to	0 11 1			Error in post-		and polished with	000 000	70	Add quality test for		1				
4.2	handle	Splinters	Injury to user	8	processing	3	Shellac	300.00%	72	the finish of the wood	<u> </u>		ļ	<u> </u>	ļ	0